



ON TIME WILDLIFE FEEDERS IS NOT RESPONSIBLE FOR VARMINT DAMAGE TO YOUR FEEDER UNIT. HEAVY SCREEN WIRE IS RECOMMENDED TO SHIELD YOUR UNIT FROM VARMINTS.

RICE BRAN FEEDER INSTRUCTIONS ITEM# 73000


STEP 1: Gently remove the hopper lid. Squeeze both sides of the white power plug and disconnect it. Set the hopper lid aside.

STEP 2: Attach the hanger bracket. To attach the hanger bracket, take one of the 3/8" bolts, slide through the hanger bracket, then slide on one of the included rubber washers. (See position in Fig. 1) Next insert the bolt through the hold on the side of the barrel. Place the fender washer then nut onto the bolt that is now extending into the inside of the barrel. (See Fig. 2) Repeat on opposite side. Slowly tighten until the hanger bracket will remain vertical without assisting/holding it vertical but can still be pivoted over for refilling the unit.

Fig. 1:



Fig. 2:



STEP 3: Install battery. *NOTE. DO NOT USE HEAVY DUTY BATTERY. USE HIGH QUALITY ALKALINE 6V LANTERN STYLE BATTERY SUCH AS ENERGIZER #529.* Remove the long bolt on the battery holder. Slide battery into position using a tilting motion. The negative battery spring will be inside the oval cut out. The positive terminal will be outside of the oval cut out near the digital timer. Once battery is in position reinstall the long battery holder screw. Connect the digital timer to the battery using the alligator clips. DO NOT CONNECT POWER CLIPS BACKWARDS. Connect the red alligator clip to the positive (+) battery spring. Connect the black alligator clip to the negative (-) battery spring. Again- Do not connect the power clips backwards.